


FEATURED JOB



Power Station Decommission

This gas fired power station in New Plymouth, New Zealand, is being decommissioned due to asbestos. KAEFER Integrated Services, who were contracted to do the scaffolding, were confronted with a spaghetti of pipes. The solution? One of the more complicated scaffolds we have seen in a long time, using over 200 tonne of gear.

“The use of the Layher system proved more flexible than other systems and aided productivity considering that we were confronted with a maze of pipe work from ground to roof,” said Paul Worrall, KAEFER Manager, Eastern States and New Zealand.

Thanks to Craig Syson, Operations Co-ordinator, KAEFER Integrated Service, for these photos.

LAYHER PTY LTD
Ph 1300 136 026
info@layher.com.au
www.layher.com.au
AUSTRALIA

Layher® 

More Possibilities. The Scaffolding System.

LAYHER LTD
Ph 0800 529 437
info@layher.co.nz
www.layher.co.nz
NEW ZEALAND